Oil Field Environmental Incident Summary

Date/Time of Notice: 12/12/2015 14:47 Incident: 20151212144722 Responsible Party: XTO ENERGY INC. Well Operator: XTO ENERGY INC. Well Name: ELK 28-4 Field Name: INDIAN HILL Well File #: 12910 **Date Incident: 12/11/2015 Time Incident: 17:00** Facility ID Number: **MCKENZIE** Twp: 153 Rna: 101 Sec: 28 Qtr: County: Location Description: Submitted By: Shawn Dahl Received By: Contact Person: Shawn Dahl 2732 Hwy 85 N Alexander, ND 58831 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Tank Overflow Release Contained in Dike: Yes - Within Dike Reported to NRC: No Spilled Units Recovered Units Followup **Units** 15 Barrels 15 Oil Barrels **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None Areal Extent: None

Potential Environmental Impacts:

None

Action Taken or Planned:

The spill was contained in an earthen berm. a vac truck cleaned up standing liquids and impacted soil will be removed.

Wastes Disposal Location: Impacted soil will be removed and taken to an approved disposal

facility, recovered liquids will be put back into the production tanks

Agencies Involved:

Updates

Date: 12/14/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.